

ENVIRONMENTAL PROTECTION AGENCY
REGION 6, UIC INSPECTION REPORT

UIC Program, P. O. Box 1495, Pawhuska, Oklahoma 74056 (918-287-4041)

Inspection Reason: Plugging

Inventory No.: 2418

Operator: Name: KWB

Address: 15 E 5th St. Suite #3300, Tulsa, OK 74103

Individual Contacted: KWB Field Sup Title: _____

Well Information:

Well Name and No. 29

Location: (b) (9)

Well Type: SWD/ER/DUAL/OTHER

Authorization: Rule/Permit/None

Authorization to Inject: Yes/No

Authorized: Pressure: _____ psi Rate: _____ BPM

Long String Casing Diameter: 5 1/2 inches Tubing Diameter: _____ inches

Base of Underground Sources of Drinking Water: 325 feet subsurface

Conditions on Inspection Date:

Lease Status: Active/Inactive

Well Status: Hooked up for injection? Yes/No Injecting? Yes/No

Required Fittings: Tubing? Yes/No Annulus? Yes/No Not Applicable

Injection Pressure: _____ psi; How Determined: _____

Annulus Pressure: _____ psi; How Determined: _____

Injection Rate: _____ bpd; How Determined: _____


Static Fluid Level:

Tubing: _____ feet subsurface; How Determined: _____

Annulus: _____ feet subsurface; How Determined: _____

Samples Taken: _____ Photographs Taken _____

Observations: squeezed bottom plugs w/ 160SV,
perforate CS4 @ 375' & circulated cement to surface



Inspection Date 11/16/93

Time: Arrived 9:30 Departed 1:00

Inspector: Rick

Evaluation: Name: David B. Jones Date: 23 Dec 93

Inspection Results 6 Follow-up A Frequency NR

Violation Code _____ Reason _____